

PRESSURE TRANSDUCER & DIGITAL DISPLAY

PRESSURE TRANSDUCER

- For precise measurement of system pressure up to 700 bar (10000 psi)
- Output 4-20 mA

Model number	Pressure reading (bar)	Pressure reading (psi)	Connection thread	Accuracy percentage full scale	Weight (kg)
HPT1	0-700	0-10000	1/4"-18 NPT	0.5	0.1

DIGITAL DISPLAY UNIT

- For use with HPT1 4-20mA pressure transducer to record pressure in applications where remote reading is preferred
- Compact size with large LCD screen
- Displays readings in bar or psi
- Features include minimum and maximum value, average value, tare offset and reset
- Complete with worldwide power supply unit
- IP65 enclosure rating
- Supplied complete with a 2 metre connecting cable

Model number	Pressure reading (bar)	Pressure reading (psi)	Screen display size (mm) L x H	Overall size (mm) L x W x H	Voltage VDC	Weight (kg)
HDD1	0-700	0-10000	76 x 25	120 x 110 x 40	18 - 32	0.3